

Vehicle Report

Specifcation

No.	Make NISSAN		Vehicle SKYLINE		Model				Score		
					E-BCNR33				R		
4458	First Registration	Displacer	nent	Type · Door	Grade			2WD	•	•	
	1996 / 3 M	260	0 сс	2D	G	aT-R		4WD	Interior Score	С	
Engine Model:	RB26DETT	Engine:	NA / 3	URBO	Model No.:	0	7824	Classification No. :	00	003	
Inspection Valid (Shaken) :			Shift Type	5F	OEM Parts	S R Leather Seat	OEM AW T V	PS) Navi	P W Airbag		
Mileage 1 2	4 , 1 5	8 Km Mile		AC	AAC	Passe	nger				
Body Base Color	Color Change		Code:	Type	7		4			Seater	
Color SILVER	-		R4	Maintenance		Recyc	ling				
Fuel Diesel F	Gasoline uel· ()		r Color : K	Book	A • (M)		1	2,150)	JPY	
Border Carbon indic	ator duct		Tein Pro 1	Tension Rod							
Nismo Clear indicator			Carrozzeri	Carrozzeria Cyber Navi							
Aftermarket Towing Hook			Nismo Triple Meter								
Hasemi Motor Sport Hood & Hood Molding			Worksbell Rapfix								
Nismo Carbon Pillar											
HKS Intercooler & Piping											
Trust Greddy Airinx											
Trust Greddy Aluminum Radiator											
Aftermarket 16 Row Oil Cooler											
RSR Equal Length Down Pipe											
SARD Catalytic Converter											
Aftermarket Muffler											
Nismo S-Tune Suspention											
Topsecret Carbon Radiator Hood											
Momo Steering Whe	el										
⊚Trust Kikaku Insp	ecton Report										
Has scuffs, stains and worn on seat.											
Right dash lower panel came off.											
Left position lamp wasn't lit.											
Right power door mirror works slow.											
Nismo triple meter doesn't work.											
(Illumination is fine on Nismo triple meter.)											
Console box isn't fixed to the car.											
A/C panel is moved inside the console box.											
I ————			i								

DEFECT REPORT

	◯ Electronic
Has scratches , cracks and scuffs on front bumper.	Left position lamp wasn't lit.
Has scratches in right rear fender.	Right power door mirror takes more time to fold.
Left rear fender has scratches and cracks on paint.	Nismo triple meter doesn't work.
Left rear under spoiler has paint bubbling and cracks.	
Trunk has scratches.	
Left rear quarter glass mall has warps.	
Has scuffs, worn and many stains on sheet.	
Right dash lower panel was came off.	
Has scartches and dent on right door.	

OTHER	RECOMMEND POINT
Left rear fender has scratches.	
Right side step has small chip.	
Console box isn't fix to the car body.	
A/C panel is installed inside the console box.	

