

Vehicle Report

Specification

No.	Iviake	Make		Vehicle		Model				ore
	NISSAN		SKYLINE			E-E	CR33			?
4652	First Registration	First Registration Displacen		nent Type · Door		Grade		2WD		
	1996 /2 M	250	0 сс	2D	GTS25	t TY	PEM	4WD	Interior Score	С
Engine Model:	RB25DET	Engine:	NA / 3	URBO	Model No.:	0	7396	Classification No. :	01	122
Inspection Valid	(Shaken):	×		Shift Type	5F	OEM Parts	S R Leather Seat	OEM AW	P S Navi	P W Airbag
Mileage 1 5	8,770	Km Mile		AC	AAC	Passe	nger	9		
Body Base Col	or Color Change	Color	Code:	Туре				2		Seater
Color WHITE				Maintenance		Recyc	ling			
Fuel	Gasoline sel Fuel · ()	1	r Color :	Book	A . (M)			12,15	0	JPY
L Die:	sel Fuel・()	1	K		<u> </u>	<u></u>				JF1
	in to have a statement and with the first to the first statement of the second					O CONTRACTOR CONTRACTO			Emphis prior nations for distribution to require security	
BCNR33 Headligh	nt, F bumper, F fender a	&Hood.								
R fender has pan	el beating	and the state of t							Magazinea roma de Principal de Servicio de Calendario de C	
Aftermarket Side	Step, R bumper.					W440000 1 200 2 400 40				Annua qualita insura contra consumato
HKS Muffler						******************		and the little plants are an analysis and a second property of the second position of the s		
APEX Aluminum	Radiator, Boost gauge,	AVC-R								
Greddy Oil Catch	Tank, Shift knob									
Aftermarkeet Air	Cleaner									
Aftermarket Coild	overs									
Aftermarket Cros	s flow inter cooler									
Aftermarket Full	Bucket Seats									
SUPER CAT Rada	ar Detector									
ECLIPSE Audio										
Aftermarket 16 In	ch Aluminum Wheel									
					part y the shakes the complete to the shakes to present the beautiful to the shakes to the shakes to the shakes				Andrew description consistency and	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
						erpopular Sometrones				***************************************
⊚Trust Kikaku lı	nspection Report		Car under	rbody is rusty	and has corro	sion.				nonetrejs betren rennesbene
Has cracks on right power window panel.			Tachome	ter is not wor	king.					
Has stains, scuffs and tear on R&L seats.			AC is not working.					Management in the second designation of the		
Has modified mark and cracks on headlight.		Front suspension has distortion.								
Battery needs replacement.		Right F instrument panel and side member								
APEX AVC-R is broken.		has sheet metal marks.								
Radar Detector is	not working.		Core supp	port and F su	oport are displ	laced.				
Audio is not work	ing.							THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.		
Left door is not o	pen and shut smoothly									
Engine is not in g	ood condition.						1	n condension werps a construction of more con-		

DEFECT REPORT

	© Electronic
Has cracks on right power window panel.	Battery need replacement.
Has scuffs, tear and stains on R & L seats.	APEXi AVCR is not working.
Has cracks and modified marks on F bumper.	Super Cat radar detector is not working.
Ha scratches and paint peeling on door mirrors.	Audio is not working.
Headlights has cracks and modified marks.	Tachometer is not working.
Has stains and paint bubbling on roof.	AC is not working.
Has scratches on left door.	
Has cracks, stains and scratches on side step.	
Has color fade and scratches around R rear fender.	
R bumper has cracks, scratches and comes off.	

OTHER		RECOMMEND POINT	
R spoiler is discolored.			
R fender is discolored.			
Has scratches and discolor o	on hood.		
Has scratches and discolor of	on hood top mold.		
Left door doesn't open and s	hut smoothly.		
Engine is not in good conditi	on.		
Has sheet metal marks on ri	ght F instrument panel		
and side member.			
Core support and F support	are replaced.		
Car underbody is rusty and h	nas corrosion.		
F suspention has distortion.			

