



# Vehicle Report

## Specification

No. <b>4852</b>	Make <b>NISSAN</b>		Vehicle <b>SKYLINE</b>		Model <b>GF-HR34</b>		Score <b>3.5</b>	
	First Registration <b>2001 / 2 M</b>	Displacement <b>2000cc</b>	Type · Door <b>4D</b>	Grade <b>20GT</b>		<input checked="" type="radio"/> 2WD · <input type="radio"/> 4WD		Interior Score <b>C</b>
Engine Model : <b>RB20DE</b>		Engine : <input checked="" type="radio"/> NA / TURBO		Model No. : <b>09056</b>		Classification No. : <b>0001</b>		

Inspection Valid (Shaken) : <b>X</b>				Shift Type <b>5F</b>		OEM Parts	S R Leather Seat	OEM AW T V	<input checked="" type="radio"/> P <input type="radio"/> S	<input type="radio"/> P <input checked="" type="radio"/> W	Navi	Airbag
Mileage	1	5	4	,	1	8	4	<input checked="" type="radio"/> Km <input type="radio"/> Mile	AC Type <b>AC</b>	Passenger <b>5</b> Seater		
Body Color	Base Color <b>Black P</b>		Color Change →		Color Code : <b>GV1</b>			Maintenance Book	<b>Y · <input checked="" type="radio"/> N</b>	Recycling <b>12,560</b> JPY		
Fuel	<input checked="" type="radio"/> Gasoline			Interior Color : <b>K</b>								


◎ Specification		
TANABE Coilovers		
Aftermarket Muffler		
Aftermarket GT Wing		
RAYS Volk Racing Gravel AV 17 Inch Wheels		
P1 Racing 17 Inch Wheels		
KENWOOD U330MS		
SPARCO Full Bucket Seat		

◎ Trust Kikaku Inspection Report		
Has stains and dirt on interior.		
Has scuffs , worn and stains on R&L seats.		
Right front power window is broken.		
Audio is not working right.		
Car underbody is rusty and has corrosion.		
Engine has abnormal sound.		

**DEFECT REPORT**

◎ Scar • Dent • Repair Part	◎ Electronic
Has scratches and clear coating peeling on hood.	Right power window is broken.
Has discolor, cracks, marks of repair on front bumper.	Audio is not working right.
Interior has scratches and stains.	
Has scratches and small dents on R&L doors.	
Has scuffs, worn and stains on R&L seats.	
All 4 wheels has scratches, stains and paint bubbling	
caused by rust.	
Has scratches on R&L door mirrors.	
Around the high mount lamp is rusty.	
Engine has abnormal sound.	
Right rear fender has cracks on paint.	

OTHER	RECOMMEND POINT
Has scratches and paint peeling on rear bumper.	
Left rear fender has scratches.	
Has scuffs and scratches on side step.	
Car underbody is rusty and has corrosion.	



A	Scar
U	Dent
B	Scar & Dent
P	Repaint Required
W	Repair Mark
S	Rust
C	Corrosion
G	Stone Chip
X	Replacement required
XX	Replaced