

Vehicle Report

Specification

No.	Make	Vehicle	Model	Score	
4866	NISSAN	180SX	E-RPS13	R	
	First Registration	Displacement	Type · Door	Grade	Interior Score
	1997 / 2 M	2,000 cc	3D	2WD · 4WD	D
Engine Model : SR20DET (Conversion)		Engine : NA / TURBO	Model No. :	Classification No. :	

Inspection Valid (Shaken) : X		Shift Type	F5	OEM Parts	S R	OEM AW	P S	P W
Mileage		Km Mile	*	AC Type	NO	Passenger	4	Seater
Body Color	Base Color	Color Change	Color Code :	Maintenance Book	Y · N	Recycling Deposit :	10,160	JPY
Fuel	Gasoline	Diesel Fuel · ()	Interior Color :					

◎ Specification		
· 7 Point Roll Cage	· HPI Air Cleaner	
· gktech Knuckle Adapter Kit	· Aftermarket Front Pipe	
· Reinforced Engine & Mission Mount	· Aftermarket Dual Muffler	
· 5H Hub (Rear Inner Drum)	· Greddy Profec	
· Greddy Intercooler	· Defi Boost Gauge	
· Aftermarket Aluminum Radiator	· Auto Gauge (Water Temp/Oil Temp/Tachometer)	
· Mechanical LSD	· TEIN Coilover	
· HKS GT-RS Turbine	· C Pillar Bar	
· TOMEI POWWERED Turbine Outlet		
· BRIDE Semi Bucket Seat		
· WORK 17 Inchi Aluminum Wheels		
· Metal Head Gasket		
· Aftermarket Exhaust Manifold		
· Engine Torque Damper		
· Front & Rear Strut Bar		

◎ Trust Kikaku Inspector Report		
Front has repair record. (T)	Interior has scars and looks worn.	One retractable headlight doesn't come up.
Audio is removed and the place stays empty.	Has scars, bent and rust underneath.	Modified odometer
Dash panel and around console lack some interior.	Oil leak from engine.	Battery trunk relocated.
Aftermarket steering wheel has scuff.	Both right and left inner panel has huge scar and	Mileage record on vehicle inspection certificate
Engine compartment is painted.	Some parts for inner panel are replaced and has	Exhausts white smoke. (Damaged turbine)
No A/C compressor.	Trunk has scars and dent.	Transmission is chagend from Automatic to Mar
Seat has marks of burn.	Lens of the front bumper has cracks.	Engine changed from NA to TB.
Recolored only in exterior.	Wheels has scars.	
All the painting is not evenly painted.	Has whole caused by corrosion on right step.	
	Tachometer is not working fine.	

DEFECT REPORT

[illegible]

OTHER

RECOMMEND POINT

[illegible]



A	Scar
U	Dent
B	Scar & Dent
P	Repaint Required
W	Repair Mark
S	Rust
C	Corrosion
G	Stone Chip
X	Replacement required
XX	Replaced