トラスト企画 Trust Kikaker

Vehicle Report

Specifcation

No.	Make	Vehicle	Model		Score
2415	NISSAN	SKYLINE	GF-HR34		R
	First Registration	Displacement / Type・Door	Grade	2WD・4WD	Interior Score: C
	2000/9 M	2000 cc / 4D	20GT		
Engine Model : RB20DE	Engine : NA / TURBO		Model No. :		Classification No. :

Inspection Valid (Shaken) : ×	Shift Type	5F	OEM Parts: S R / Leather Seat	OEM AW: T V	P S: Navi	P W: Airbag
Mileage 155,927 Km / Mile	AC Type	AAC	Passenger: 5 Seater			
Body Color: Base Color Gray → Color Change / Color Code : WV2	Maintenance Book	Y・N	Recycling: 12,560 JPY			
Fuel: Gasoline / Diesel Fuel・( ) / Interior Color : K						

◎ Specifcation		
BBS WISer 17 Inches Wheels		
Auto Gauge Meters (Vacuum, Tacho, Electric)		
SONY NVX-Z 555 HDD Navigation System		
PANASONIC ETC		

◎Trust Kikaku Inspecton Report		
Steering wheel has scuffs.		
Has wrinkle on seat.		
Muffler has bent.		
Underneath the car is rusty.		
Wheels has scratches and looks worn.		
Has repair marks on left front inner panel		
and core support.		
Trunk opener doesn't work fine.		
Body paint is discolored.		

DEFECT REPORT

◎ Scar・Dent・Repir Part	◎ Electronic
Has dent and cracks on front bumper	
and it doesn't fit right.	
Muffler is bent.	
Left front inner panel and core support has repair marks.	
Right front fender has scars.	
Left rear fender has scuffs.	
Rear bumper has scuffs, cracks and dent.	
Car underneath is rusty.	
Has dent and scuffs on left side step.	
Has dent on right side step.	

OTHER	RECOMMEND POINT

2415



Spare

A	Scar
U	Dent
B	Scar & Dent
P	Repaint Reqired
W	Repair Mark
S	Rust
C	Corrosion
G	Stone Chip
X	Replacement required
XX	Replaced