

## **Vehicle Report**

**Specification** 

						0000	moution		
No.	Make		Vehicle		Model	Score			
NISSAN		I	SKYLINE		GF-ENR34			3.5	
3354	First Registration Displace		cement Type · Door		Grade		2WD		
	2001/4M	2500cc		4D	25GT-X	( FOUR	(4WD)	Interior Score	С
Engine Model:	RB25DE	Engine: NA /		TURBO	Model No. :	09058	Classification No. :	000	)1

Inspectio	on Valid (Shaken)		$\overline{\mathbf{v}}$	Shift Type	5F	OEM	S R	OEM AW	(PS)	(PW)
		<u> </u>		ЭГ	Parts	Leather Sea	t TV	Navi	Airbag	
Mileage		135,031	L Km Mile	AC	AAC	Passe	nger	5	-	
Body	Base Color C	Color Change	Color Code :	Туре				le l	)	Seater
Color	PEARL	Bayside Blue				Recyc	ling			
Fuel	Fuel		Interior Color :	Maintenance Book	Y • (N)		•	12,66	Λ	
1 461	Diesel Fuel $\cdot$ (	( ) <b>K</b>			)		-	12,00	U	JPY

## DEFECT REPORT

◎ Scar • Dent • Repir Part	◎ Electronic
$\cdot$ Has scratches underneath the front bumper.	• Nothing in particular.
• Has paint peeling on front bumper.	
$\cdot$ Front fender has rust and corrosions partially.	
• Rear bumper has paint cracks and peeling.	
• Mounting part has problem on rear bumper.	
$\cdot$ Has holes for mounting OEM wing on trunk.	
• Has corrosions on left rear door.	
• Has corrosions on left front fender partially.	

OTHER	RECOMMEND POINT				
$\cdot$ Has rust and corrosions on right & left strut area.	• Popular 4-door MT 34 skyline!				
• Car underbody is rusty and has corrosions.	• RARE grade! 2.5L 4WD ENR34!				
• Repainted entire car. (TV2)	• Repainted entire car! Popular bayside bule color!				
• Engine has abnormal sound.	• NISMO F bumper, S step and R bumper installed!				
	$\cdot$ 17 inch BBS RE-V Aluminum wheels installed!				
	• Good for drift car base.				

