




**DEFECT REPORT**

◎ Scar • Dent • Repair Part	◎ Electronic
• Front bumper has huge scratch,	• Door mirror power folding is not working.
• Has dent on roof.	
• Has white stain on right side door.	
• Around-the-door area has repair marks.	
• Has scratches on rear bumper.	
• Has scratches and stains inside the cabin.	
• Has rust and corrosions underneath.	

**OTHER****RECOMMEND POINT**

• Has warp and cut on dashboard.	• Fully normal OEM 4 speed car!
• Has color fade on body.	• How about having this car as a base car?



A	Scar
U	Dent
B	Scar & Dent
P	Repaint Required
W	Repair Mark
S	Rust
C	Corrosion
G	Stone Chip
X	Replacement required
XX	Replaced