



Vehicle Report

Specification

No. 4997	Make NISSAN	Vehicle SKYLINE	Model GF-ENR34		Score 2	
	First Registration 2000/3M	Displacement 2500cc	Type · Door 2D	Grade 25GT FOUR	2WD 4WD	Interior Score C
Engine Model : RB25DE		Engine : NA / TURBO		Model No. : 09058	Classification No. : 0013	

Inspection Valid (Shaken) 2021/12M		Shift Type 5F		OEM Parts	S R Leather Seat	OEM AW T V	P S Navi	P W Airbag
Mileage 138,441 Km Mile			AC Type AAC	Passenger 5 Seater				
Body Color SILVER	Base Color SILVER	Color Change →	Color Code : KR4	Maintenance Book Y · N	Recycling 12,560 JPY			
Fuel Gasoline	Diesel Fuel · ()		Interior Color : G					

◎ Specification		
· KENWOOD Car Navigation & ETC		
· RAZO Aluminum Pedal Cover		
· Aftermarket Shift Knob		
· SPEED STAR 19 inch Aluminum Wheel		
· OEM Optional ALTIA Aero		
· 5Zigen Muffler		

◎ Trust Kikaku Inspection Report		
· Very rusty underneath and has corrosions.		
· Has rust on strut tower.		
· Rear piece tip has dent on muffler.		
· Has dent on jack points.		
· Has tear, scuffs and worn on seat.		
· Interior has stains.		
· Has repair marks on floor.		
· Body color is faded.		
· Better to check actual car.		


DEFECT REPORT

☉ Scar • Dent • Repair Part	☉ Electronic
• Has scratches on front bumper.	
• Has dent on hood.	
• Has repair marks on floor.	
• Has paint bubbling on front left fender.	
• Has scratches on both right & left fenders.	
• Has rust and paint bubbling around right door mirror.	
• Has scratches and paint peeling on left door mirror.	
• Has rust and repair marks on mounting part of rear wing.	
• Has scratches on rear bumper.	
• Has dent on muffler rear piece side.	

OTHER

RECOMMEND POINT

• Interior has stains.	• Rare OEM Optional ALTIA Aero installed!
• Around strut tower is rusty.	• OEM 5 speed, 2-door car!
• Has clear coating peeling on headlight.	• How about having this car for base?
• Underneath is rusty and has lots of corrossions.	
• Has dent on jack points.	
• Has scuffs and tear on seat.	
• Has scuffs and tear on steering wheel.	
• Body color is faded.	
• Please check actual car before purchasing.	



A	Scar
U	Dent
B	Scar & Dent
P	Repaint Required
W	Repair Mark
S	Rust
C	Corrosion
G	Stone Chip
X	Replacement required
XX	Replaced

4997