

## **Vehicle Report**

**Specification** 


5037

Make				Vehicle	Model	Type/Door
NISSAN				FAIRLADY Z	UA-Z33	3D
First Regist	ration			Displacement	Grade	
2003	/	3	M	3500 🤐	BASE	2WD

Score				
3	.5			
Interior	_			
Score	C			

Inspection Valid (Shaken)			X <sub>Y</sub>		X	М	Shift Type					
Mileage 1		1	1	6	,	3	2	9	km		F	AT.
Body	Base	Colo	r		Co	lor (	Char	nge	Colo	r Code		
Color	SIL\	/ER		-					К	Υ0	AC Type	AC
Fuel		(	30	sol	ine			Printer Street, St.	Interi	or Color		
G												
Recycling Deposit				Passeg	er	Book	YES					
12,870 <sub>JPY</sub>					2	Seater						

OEM	S R	OEM AW	P S	P W				
PARTS	Leather Seat	ΤV	Navi	Airbag				
Spece	<b>○</b> Specification							
• Nismo	-like Rear	Spoiler						
· OEM C	ptional L	ED Taillamp						
· Z34 RA	YS 19 inc	ch Wheels						



			S
A	Scar	S	Rust
U	Dent	С	Corrosion
В	Scratche & Dent	G	Stone Chip
P	Repaint Required	X	Replacement Required
W	Repair Mark	XX	Replaced

## ✓ Trust Kikaku Inspection Report

- · Interior has scratches and stains.
- · Has scuffs on seat.
- · Has rust underneath.

Engine	VQ35DE
NA/TURBO	NA
Model No.	11541
Classification No.	0038

⊚ Scar · Dent · Repir Part	© Electronic
· Has scratches on front bumper.	
· Has stains on right side door.	
· Has small dents on both right & left doors.	
· Has repair marks on right rear fender.	
Has scratches on roof.	
· Has scratches on rear bumper.	
· Has paint cracks and scratches on rear gate.	
· Has dent on left rear fender.	

OTHER	RECOMMEND POINT
· Interior has stains.	• Fully normal car!
· Has scuffs and peeling on steering wheel.	· OEM Optional parts are installed!
· Has scuffs and worn on seats.	
· Has scratches on right door inner handle.	
· Has paint color fade around roof.	