


## Vehicle Report

### Specification

No. <b>5622</b>	Make <b>NISSAN</b>	Vehicle <b>180SX</b>	Model <b>E-RPS13</b>	Type/Door <b>3D</b>	Score <b>4</b>
	First Registration <b>1998 / 4</b> <small>M</small>	Displacement <b>2000</b> <small>cc</small>	Grade <b>TYPE X</b>	<b>2WD</b>	

Inspection Valid (Shaken) <b>X</b> Y <b>X</b> M	Shift Type <b>F5</b>
Mileage <b>97,919 km</b>	AC Type <b>AAC</b>
Body Color Base Color <b>White</b> → Color Change Color Code <b>326</b>	
Fuel <b>Gasoline</b>	Interior Color <b>GRAY</b>
Recycling Deposit <b>10,060</b> <small>JPY</small>	Passenger <b>4</b> <small>Seater</small>

OEM PARTS	S R	OEM AW	P S	P W
	Leather Seat	T V	Navi	Airbag
<b>◎ Specification</b> <ul style="list-style-type: none"> <li>Hub 4 holes changed to 5 holes.</li> <li>GP SPORTS EXAS Muffler</li> <li>Aftermarket Dashboard Cover</li> <li>HKS Power Flow &amp; Direct Suction</li> <li>HKS Hipermax Coilover</li> <li>DEFI Link Meter</li> <li>Aftermarket Aluminum Radiator</li> <li>Aftermarket Tension Rod</li> </ul>				



<b>✓ Trust Kikaku Inspection Report</b> <ul style="list-style-type: none"> <li>Has scratches and stains on the interior.</li> <li>Has damage on jack point.</li> <li>Has rust underneath.</li> <li>Comes with Inspection record book.</li> </ul>	
Engine	SR20DET
NA/TURBO	TURBO
Model No.	06723
Classification No.	0092

A	Scar	S	Rust
U	Dent	C	Corrosion
B	Scratche & Dent	G	Stone Chip
P	Repaint Required	X	Replacement Required
W	Repair Mark	XX	Replaced

**DEFECT REPORT**

© Scar • Dent • Repir Part	© Electronic
• Has scratches and cracks on front bumper.	• Malfunctioning only oil pressure gauge.
• Has scratches on rear bumper.	

**OTHER****RECOMMEND POINT**

• Has scratches and stains on the interior.	• 180 SX Good conditon!!
• Body color has once repainted.	• Changed to 5 holes! You can customise to
	various wheels!
	• Beautiful body!